






CINTROPUR[®] NW 50

SLEEVES 5, 10, 25, 50 & 100 µm






PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 62

SLEEVES 5, 10, 25, 50 & 100 µm






PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 75

SLEEVES 5, 10, 25, 50 & 100 µm




PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR® NW 50/62/75

SLEEVES 150 µm nylon




**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
 PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR® NW 50/62/75

SLEEVES 300 µm nylon




**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
 PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] NW 50/62/75 TE

with activated carbon - NORIT ROW 0.8 SCIN

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 50/62/75 TE

with POLYPHOSPHAT (SILIPHOS)

**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
 PRESSURE DROP - PERDIDA DE CARGA**

