








# CINTROPUR<sup>®</sup> NW 18

## SLEEVES 5, 10, 25, 50 & 100 µm

### PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA











# CINTROPUR<sup>®</sup> NW 25 with connection 3/4"

**SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon**

**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST  
PRESSURE DROP - PERDIDA DE CARGA**






# CINTROPUR® NW 25 1"


## SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon

### PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm




SLEEVE 25 µm




SLEEVE 50 µm



SLEEVE 100 µm



SLEEVE 150 µm nylon (washable)







# CINTROPUR® NW 25 1" and 3/4"

## UNIVERSAL CARTRIDGE

### PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA







# CINTROPUR<sup>®</sup> DUO 25

with ACTIVATED CARBON - NORIT ROW 0.8 SCIN

## PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA






# CINTROPUR<sup>®</sup> DUO 25

with SILIPHOS

## PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA







# CINTROPUR<sup>®</sup> DUO 25

## WITHOUT ANY PELLETS

### PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA







# CINTROPUR<sup>®</sup> NW 25/32 TE

with activated carbon - NORIT ROW 0.8 SCIN

## PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA







# CINTROPUR® NW 25/32 TE

with POLYPHOSPHAT (SILIPHOS)

## PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA




# CINTROPUR<sup>®</sup> NW 32


## SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon

### PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm




SLEEVE 25 µm



SLEEVE 50 µm



SLEEVE 100 µm



SLEEVE 150 µm nylon (washable)

