






CINTROPUR[®] NW 18

SLEEVES 5, 10, 25, 50 & 100 µm







PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 25 with connection 3/4"

SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon







**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
 PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] NW 25 1"

SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon



**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
 PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] NW 25 1" and 3/4"

UNIVERSAL CARTRIDGE



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] DUO 25

with ACTIVATED CARBON - NORIT ROW 0.8 SCIN



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] DUO 25

with SILIPHOS



**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] DUO 25

WITHOUT ANY PELLETS



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 25/32 TE

with activated carbon - NORIT ROW 0.8 SCIN



PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 25/32 TE

with POLYPHOSPHAT (SILIPHOS)

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA



CINTROPUR[®] NW 32

SLEEVES 5, 10, 25, 50 & 100 µm + 150 µm nylon

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA

