




CINTROPUR® NW 50


SLEEVES 5, 10, 25, 50 & 100 µm

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA


SLEEVE 5 µm




SLEEVE 10 µm




SLEEVE 25 µm



SLEEVE 50 µm



SLEEVE 100 µm










CINTROPUR® NW 62

SLEEVES 5, 10, 25, 50 & 100 µm

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA










CINTROPUR[®] NW 75

SLEEVES 5, 10, 25, 50 & 100 µm

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA








CINTROPUR® NW 50/62/75

SLEEVES 150 µm nylon

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA








CINTROPUR® NW 50/62/75

SLEEVES 300 µm nylon




**PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST
PRESSURE DROP - PERDIDA DE CARGA**



CINTROPUR[®] NW 50/62/75 TE

with activated carbon - NORIT ROW 0.8 SCIN

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA





CINTROPUR® NW 50/62/75 TE

with POLYPHOSPHAT (SILIPHOS)

PERTE DE CHARGE - DRUKVERLIES - DRUCKVERLUST PRESSURE DROP - PERDIDA DE CARGA

